

# Using Data to Improve Safety

Captain Jay Cormican  
Sr. Manager Fleet Standards-B787  
United Airlines

## 利用数据提高安全性


Jay Cormican机长  
美国联合航空公司B787标准机队高级经理




- We have access to more data than ever before  
可用数据量超过以往
- Finding useable data is challenging  
获得有效数据越来越具挑战性
- The flow of data has changed over time  
数据流随时发生变化

1110101100100011010110000110100010110  
1001110101100100011010110000110100010  
1101001110101100100011010110000110100  
0101101000111010110001011000101000111  
0100100101100111010110010001101011000  
0110100010110100111010110010001101011  
0000110100010110100111010110010001101  
0110000110100010110100111010110010001  
1010110000110100010110100011101011000  
1011000101000111010010010110011101110  
0010010100111011011011011101101100101  
0100001111010111010001101001001101110  
1011001110110101110011001110100111001  
1101001001011001110101100100011010110  
0001101000101101001110101100100011010  
1100001101000101101001110101100100011  
0101100001101000101101001110101100100  
0110101100001101000101101000111010110  
0010110001010001110100100101100111010  
1100100011010110000110100010110100111  
0101100100011010110000110100010110100  
1110101100100011010110000110100010110  
1001110101100100011010110000110100010  
1101000111010011101001001011001110101  
1001000110101100001101000101101001110  
1011001000110101100001101000101101001  
1101011001000110101100001101000101101  
0011101011001000110101100001101000101  
1010001110101100010110001010001110100  
1001011001110101100100011010110000110  
1000101101001110101100100011010110000  
1101000101101001110101100100011010110  
0001101000101101001110101100100011010  
1100001101000101101000111010101110101  
1101100010101111010111101011011010001  
1011100101101110010100011101011011010  
1100110011101010001000111001000111001

# Then 以往



Now  
现在



# B737 Tail Strike

## B737机尾擦地

- Analyzed event data in the 737-900ER fleet and found correlation between tail strike and power-on landing  
分析737-900ER事件数据，找到机尾擦地和带油门着陆间的相关性
- Reduced power-on landings from 7% to less than 1% and as a result reduced tail strike occurrences  
将带油门着陆间发生率从7%减少到不足1%，从而降低机尾擦地发生率

# B787 Tire Overspeed

## B787 轮胎超速

- FOQA data indicated tire overspeeds when departing DEN at heavy weights and during hot weather  
飞行品质监控数据显示，离开**DEN**时，在重物和炎热天气下状况下轮胎会超速
- Analysis revealed rotation was initiated up to 3 seconds after Vr and rotation rate of 1.8°/sec in overspeed events  
分析表明，在超速情况下，Vr和旋转率1.8°/秒，旋转上升至3秒
- Reduced DEN tire overspeed rate from 16% to 3% YOY  
**DEN**轮胎超速率从16%减少到3%（按年计算）

# RNV RNP Approach Transitions

## RNV RNP进近过渡


- FSAP data and ATC pilot deviation reports indicated an issue with flying RNAV RNP approach transitions  
FSAP数据和ATC飞行员偏差报告显示，RNAV RNP进近过渡存在问题
- Data highlighted several contributing factors:  
数据重点提及了几个影响因素：
  - Late approach assignment by ATC  
ATC分配的深进近任务
  - Pilots briefing and programming the ILS rather than RNAV  
飞行员概述和编写ILS而非RNAV
  - FMC programming difficult to do on short notice  
短期内编写FMC困难重重
- Reduced occurrences by over 50% YOY  
减少50%以上的发生率（按年计算）





# Using Data Proactively 主动地使用数据

- FOQA Study-787 Landings  
FOQA研究-787着陆
- Utilized FOQA data to determine:  
利用FOQA数据确定:
  - Threshold Crossing Height  
跑道入口通过高度
  - Speed at touchdown  
接地速度
  - Touchdown Point  
接地点
  - Thrust reverser and autobrake use  
反推装置和自动制动装置的使用
  - Runway exit location and speed  
跑道出口位置和速度






# 787 Crossing Heights



## 787通过高度

Fleet Average:  
机队平均值:



# 787 Threshold to Touchdown

## 787跑道入口至接地点




■ 787-8 ■ 787-9 ■ 787-10

# 787 Thrust Reverser Deployed After Touchdown

## 接地后787反推力装置部署




Measurement 衡量	Fleet Average 机队平均值
Average Thrust Reverser Deployment 平均推力反向器部署	15.66 Seconds 15.66秒
Time from Sustained WOW to T/R Commanded 从持续WOW到T/R命令的时间	4 Seconds 4秒
Groundspeed of T/Rs Commanded Stowed T/R命令装舱的地速	68.4 knots 68.4节
Groundspeed of T/Rs Stowed T/R装舱的地速	59.6 knots 59.6节



# 787 Autobrake Disengaged Groundspeed

## 787自动制动地速



# Ongoing FOQA Studies

## FOQA现阶段研究

- B737 Speed at runway exit  
B737跑道出口速度
- All Fleet Harmonization  
各机队协调
- High rates of descent below 500'  
500' 以下下降率高
- Flight Level Change (FLCH) below 1000'  
1000' 以下飞行高度层更改 (FLCH)
- Airspeed decay below Vref  
Vref以下空速衰变

# Taking Action

## 采取行动



## Team 787 Conference Call



October 3, 2019

UNITED 



**Thank you**  
**谢谢**

谢谢

**Questions?**  
**欢迎提问！**